5.6 City of Hialeah

A map of the City of Hialeah was submitted to the Task Force, and can be found in Appendix Q.

Comments excerpted below are from the January 18, 2000 meeting of the Flood Management Task Force:

After Hurricane Irene, homes were not flooded, however there were sanitary problems associated with the sewage backflows. The water receded within 36 hours after the storm passed. The City of Hialeah needs more resources and more water storage capacity.

Further information on the City of Hialeah can be found in Appendix O.

Please refer to the maps at the beginning of Chapter 5 for the locations of each trouble area within the north, central and south parts of Miami-Dade County.


5.7 City of North Miami

The City of North Miami experienced the following problems during the aftermath of Hurricane Irene:



Power failure occurred at Stormwater Pump

Station E, located at NE 12th Ave. and NE 143 St., a back up CNG pump could not keep up with the flows. Within twenty-four hours of power restoration most of the affected areas were dry or pumped out. Consequently, the Ruck's Park Pump Station service area was dry within twenty-four hours after the power was restored.



that time due to downed power lines.

Based on the magnitude of the event, City residents fared well. FPL responded as soon as winds died down, but could not restore power at



Further information and a map of flooded areas of North Miami can be found in Appendix P.

Please refer to the maps at the beginning of this Chapter to locate this City in the north, central or south part of Miami-Dade County.